Attorney's Docket No.: 110348-135355 Patent

IPN: P15049

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: Tuan Thieu Lam

Art Group: 2816

Confirmation No. 5704

In re Application for:

Cole et al.

Application No.: 10/750,558

Filed: 12/31/2003

Patent No.: 7,038,505 B2

Issued: 05/02/2006

For: CONFIGURABLE ENABLING

PULSE CLOCK GENERATION FOR MULTIPLE SIGNALING

MODES

Attn: Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

Upon review of the above-referenced Letters Patent, Applicant noted errors that are the mistake of the U.S. Patent and Trademark Office and the Applicant. Those errors are as follows:

Figure 1

[Ref no.] 24...PULSE CLCOK... should read --...PULSE CLOCK...--

Column 3

Line 17, "...earlier, 16 latch banks 26..." should read --...earlier, 16 [no bold] latch banks 26...-.

Line 45, "...via **16** corresponding..." should read --...via 16 [no bold] corresponding...-.

Column 5

Line 32, "...a glitch design may..." should read --...a glitch design 168 may...-.

Line 63, "...StbP 204 and StbN 206..." should read --...StbP214 and StbN

216...-.

Included with this submission is a Certificate of Correction and it is respectfully requested that a Certificate of Correction be issued. This request for correction is made under the provisions of 37 CFR 1.322 and 1.323.

Payment by Deposit Account No. 500393 is included in the amount of \$100.00 for the fee as set forth in 37 CFR § 1.20(a).

Respectfully submitted, SCHWABE, WILLIAMSON & WYATT, P.C.

Dated: 06/25/2007

/Angela M. Sagalewicz/ Angela M. Sagalewicz Registration No. 56,113

Pacwest Center, Suite 1900 1211 SW Fifth Avenue Portland, Oregon 97204 Telephone: 503-222-9981 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page <u>1</u> of <u>1</u> PATENT NO. : 7,038,505 B2 APPLICATION NO.: 10/750,558 ISSUE DATE : 05/02/2006 INVENTOR(S) Cole et al. It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below: Figure 1 [Ref no.] 24...PULSE CLCOK... should read --...PULSE CLOCK...--Column 3 Line 17, "...earlier, 16 latch banks 26..." should read --...earlier, 16 [no bold] latch banks 26...-. Line 45, "...via 16 corresponding..." should read --...via 16 [no bold] corresponding...-. Column 5 Line 32, "...a glitch design may..." should read --...a glitch design 168 may...-. Line 63, "...StbP 204 and StbN 206..." should read --...StbP214 and StbN 216...-.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

SCHWABE, WILLIAMSON & WYATT, P.C. 1211 SW Fifth Avenue, Suite 1900 Portland, OR 97204

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.